

SAFETY ADVISORY NOTICE

X-TREME GUSTI BOYS & GIRLS WINTER COATS

POSSIBLE HAZARD

As part of Sears' ongoing commitment to product quality, we have determined through our internal quality assurance program that the drawstring functionality on the X-Treme Gusti coats, may pose a potential strangulation hazard.

IDENTIFICATION

The affected coats were sold between February 2008 and September 2008 in sizes 8-18. The affected style numbers are listed below, and may be found on the garment label either in the neck or in the internal side seam of the garment.

Retail Item #	Manufactur #	Item Description	Selling
39300	JS8G1574	Girls 3 in 1 Jacket	59.99
39301	JS8G1574	Girls 3 in 1 Jacket	59.99
38272	JS885176	Boys 3 in 1 Jacket	59.99
38273	JS885176	Boys 3 in 1 Jacket	59.99
39409	EW8G5177	Girls 2 pc Snowsuit	89.97
38423	EW8B5176	Boys 2 pc Snowsuit	89.97
91805	EW8G5177	Girls 2pc Snowsuit	89.97
91804	EW8B5176	Boys 2pc Snowsuit	89.97
91180	XWG3032	Girls 2pc Snowsuit	99.99/149.99
91181	XWG3031	Girls 2pc Snowsuit	99.99/149.99
91166	XWB3037	Boys 2pc Snowsuit	99.99/149.99
91167	XWB3037	Boys 2pc Snowsuit	99.99/149.99
88268	JW8G5273	Girls Parka	79.99/99.99
88269	JW8G5273	Girls Parka	79.99/99.99
88266	JW8B5276	Boys Parka	79.99/99.99
88267	JW8B5276	Boys Parka	79.99/99.99

CORRECTIVE ACTION

In the interest of consumer safety, Sears Canada advises customers who own this coat to please remove all elastic draw cords found on the hood of your jacket. Fully extend each draw cord to its maximum length, and cut the cords as close to the eyelet as possible. (please see attached diagram).

Sears Canada is bringing this matter to your attention in the interest of consumer safety and apologizes for any inconvenience this may cause you.

REMOVE HOOD ELASTIC

FRONT HOOD ELASTIC

1

Stretch to the maximum both elastic cords on one side of the hood and cut them.



2

On the other side, remove the free elastic cord & pull to the maximum the remaining one. Cut the cord close to the eyelets



BACK HOOD ELASTIC

1

Stretch to the maximum both elastic cords and cut them close to the eyelet.



DK